



8,234
Hours

6,013 Landings



Highlights

- Engines Enrolled on CSP Gold
- APU Enrolled on MSP Gold
- HUD, FDR, CVR
- Recent Paint and Interior
- 10 Passenger Configuration

Airframe

TOTAL TIME SINCE NEW	8,234 Hours (as of August 2024)
TOTAL LANDINGS SINCE NEW	6,013 Landings
ENTRY INTO SERVICE DATE	January 2001
CERTIFICATION	EASA

Engines	Left	Right
DESCRIPTION	CFE Company CFE	E738-1-1B
SERIAL NUMBERS	P105423	P105416
TOTAL HOURS SINCE NEW	7,997 Hours	7,997 Hours
TOTAL CYCLES SINCE NEW	5,842 Cycles	5,842 Cycles
PROGRAM COVERAGE	CSP Gold	

APU

DESCRIPTION	Honeywell 36-150
SERIAL NUMBER	P-227
APU TOTAL TIME SINCE NEW	6,061 Hours
PROGRAM COVERAGE	MSP Gold

Avionics

The Falcon 2000 is equipped with an integrated, Collins Pro Line 4 avionics suite.

Notable features

HUD	FDR

CVR



Interior

NUMBER OF PASSENGERS	Ten (10)
GALLEY LOCATION	Fwd
FWD CABIN CONFIGURATION	Four (4) Place Club
	Four (4) Place Conference Group opposite Two
AFT CABIN CONFIGURATION	(2) Place Club
LAVATORY LOCATION	1 11


Exterior

BASE PAINT COLORS	White & Dark Blue
LAST PAINTED DATE	2022

Major inspection status

Inspection	Last Performed	Next Due
12 Month	November 2023	October 2024
24 Month	October 2022	October 2024
36 Month	November 2021	November 2024
72 Month	November 2018	November 2024
144 Month	September 2012	September 2024

Floorplan



























registration marks, or other identifying information to protect the privacy of the Aircraft's current owner. The Aircraft is subject to prior sale, lease, and/or removal from the market without prior notice.







FOR YOUR WORLD